



GENERAL AVIATION SERVICES, LLC



# AIRCRAFT SPECIFICATIONS

## 1992 DASSAULT FALCON 900B

SERIAL NUMBER:	0111	HOURS TOTAL TIME:	8,522.6
REGISTRATION:	TS-JSM	LANDINGS:	4,355
<b>ENGINES:</b> GRT TFE731-5BR-1C Engines <b>MSP GOLD</b>	Engine 1: Serial Number P101114C 8,367.2 Hours Total Time 4,242 Cycles Since New	Engine 2: Serial Number P101109C 8,065.5 Hours Total Time 4,092 Cycles Since New	Engine 3: Serial Number P101118C 8,172.3 Hours Total Time 4,153 Cycles Since New
APU:	Garrett GTCP36-150(F) Serial Number P226	3,710 Hours Total Time 3,222 Cycles	<b>MSP Gold</b>
FEATURES:	<div> <ul style="list-style-type: none"> <li>• Engine DEEC's Installed</li> <li>• 8.33 Spacing</li> <li>• RNP-5</li> <li>• Thrust Reversers</li> <li>• Upgrade RAAS Mute</li> <li>• Cabin Exhaust System</li> </ul> </div> <div> <ul style="list-style-type: none"> <li>• FM Immunity</li> <li>• RVSM Compliant</li> <li>• RNP-10</li> <li>• Runway Awareness and Advisory Switch System (RAAS)</li> <li>• Emergency Vision Assurance System (EVAS)(2 Units)</li> </ul> </div>		
AVIONICS:	<div>           Flight Management System:            Flight Director:            Autopilot:            Communications:            Navigation:            Automatic Direction Finder:            Transponder:            Distance Measuring Equipment:            Radar:            Radio Altimeter:            High Frequency Communication:            AFIS:            INS/IRS:            Global Positioning System:            Traffic Collision:            Cockpit Voice Recorder:            Flight Data Recorder:            EGPWS:            SATCOM 1:            SATCOM 2:            Flightfone:            Stormscope:            Emergency Locator Transmitter:         </div> <div>           Dual Honeywell NZ-2000 with 6.0 software            Dual Honeywell SPZ-8000            Honeywell SPZ-8000            Triple Collins VHF-22D            Dual Collins VIR-32            Dual Collins ADF-60A            Dual Bendix King MST-67A            Dual Collins DME-42            Honeywell WV-870            Honeywell RT-300            Dual King KHF-950            Allied Signal SAT AFIS            Triple Honeywell Laser Ref            Honeywell 12 Channel            Bendix/King CA5-81            L3 - JAR OPS/EASA Ready            L3 - JAR OPS/EASA Ready            Sundstrand Mark V Enhanced            Honeywell MCS-3000            True North with wireless handsets            MagnaStar C-2000            BFG Stormscope WX-1000            Artex 110-406         </div> <p><b>Covered by Honeywell HAAP contract</b></p>		

Aircraft offered subject to prior sale, inspection, verification of specifications and withdrawal from market. REV090712mjh



# 1992 FALCON 900B

MAINTENANCE:	<ul style="list-style-type: none"><li>• 2C Inspection Complied With June 2009 at Standard Aero, Springfield, Illinois</li><li>• Next C Inspection Due June 2015</li><li>• Landing Gear Overhaul Due March 2016</li><li>• C/W optional Service Bulletins: SB F900-112, SBF900-209 &amp; SBBF900-315</li></ul>
INTERIOR:	<p>Completely refurbished June 2009 at StandardAero, Springfield, Illinois. Fourteen passenger fireblocked interior completed in light and dark Tan leather with diamond design inset, including eight new DeCrane chairs – four in forward club configuration and four in mid-cabin club configuration. Aft left-hand side and right-hand side three place berthable divans. AeroBax seat foam used in chairs and divans.</p> <p>Upgraded cabin headliner and valance overlay panel modifications and LED lighting upgrade. Mid-ship pocket door. All new cabin hardware including latches and plating, forward cabin hinged door. Galley contains annex catering storage modification, galley drawer modification and new ovens. Espresso coffee machine installed and certified. All new woodwork completed in high gloss finish with new veneer. New Cambria Quartz countertops were fabricated and installed in the galley, including the pop-out work surface and sink cover.</p> <p>Completely refurbished forward and aft lavatories including New Cambria Quartz vanity countertops, new woodwork and new upholstery.</p> <p>Rosen Cabin Management System includes ten Rosen Ultra Touch-Screen Passenger Control Units and one Ultra Touch-Screen Passenger Control Unit located in the galley. Entertainment equipment includes two new Rosen DVD players, two Rosen DVD remote controls and IR sensors to provide separate remote control for the DVD players only. Alto Technologies cabin audio system and cabin stereo speaker system. Cabin plug-in monitors: eight new 10" plug-in monitors with arms. Cabin bulkhead monitors: one new Rosen 20" LCD monitor in the forward cabin. New cabin 50 Hz AC Inverter, new AC switched outlets and cabin systems master power control switch.</p> <p>Aft baggage area completely refurbished.</p>
EXTERIOR:	<p>Overall White and Khaki with Las Vegas Gold stripes. Completed new by StandardAero, Springfield June 2009.</p>


***Aircraft Sales, Brokerage, Acquisitions & Consulting***



*Aircraft offered subject to prior sale, inspection, verification of specifications and withdrawal from market. REV090712mjh*



# 1992 FALCON 900B







GENERAL AVIATION SERVICES, LLC



Aircraft Specifications - Falcon 900B, S/N 0111  
Continued Page 4 of 6

## 1992 FALCON 900B



1155 Ensell Road • Lake Zurich, Illinois 60047  
www.GenAv.com • sales@GenAv.com

**GenAv.com**

• ph: 847-726-5000 • fx: 847-726-7673





GENERAL AVIATION SERVICES, LLC



Aircraft Specifications - Falcon 900B, S/N 0111  
Continued Page 5 of 6

## 1992 FALCON 900B



1155 Ensell Road • Lake Zurich, Illinois 60047  
www.GenAv.com • sales@GenAv.com

**GenAv.com**

• ph: 847-726-5000 • fx: 847-726-7673





GENERAL AVIATION SERVICES, LLC



Aircraft Specifications - Falcon 900B, S/N 0111  
Continued Page 6 of 6

## 1992 FALCON 900B



1155 Ensell Road • Lake Zurich, Illinois 60047  
www.GenAv.com • sales@GenAv.com

**GenAv.com**

• ph: 847-726-5000 • fx: 847-726-7673