



GENERAL AVIATION SERVICES, LLC



AIRCRAFT SPECIFICATIONS

2000 CITATION EXCEL

SERIAL NUMBER:	5135	REGISTRATION:	N885BB
HRS. TOTAL TIME:	8,184.5	LANDINGS:	5,106
ENGINES: Pratt & Whitney PW545A	<div>Left Engine:</div> <div>Serial Number PCE-DB0278</div> <div>8,043 Hours Total Time</div> <div>2,824.2 Hours Remain to Overhaul</div> <div>324.2 Hours Remain to Hot Section</div> <div>Right Engine:</div> <div>Serial Number PCE-DB0277</div> <div>8,034 Hours Total Time</div> <div>1,734.5 Hours Remain to Overhaul</div> <div>1,734.5 Hours Remain to Hot Section</div>		
APU:	<div>Honeywell RE100 (XL)</div> <div>Serial Number P-187</div> <div>3,390.9 Hours Total Time</div>		
FEATURES:	<div>• EROS Crew Oxygen Masks</div> <div>• Lead Acid Battery</div> <div>• Meggit Standby Display</div> <div>• Externally Servicing Lav</div> <div>• Precise Pulselight System</div> <div>• RVSM Compliant</div> <div>• AHRS</div>		
AVIONICS:	<div> <div>Navigations:</div> <div>Automatic Direction Finder:</div> <div>Flight Director System:</div> <div>Electronic Flight Instrument System:</div> <div>Flight Management System:</div> <div>Auto Pilot:</div> <div>Altimeter:</div> <div>Distance Measuring Equipment:</div> <div>Cockpit Voice Recorder:</div> <div>Air Data Computer:</div> <div>SATCOM:</div> <div>Communications:</div> <div>Traffic Collision Avoidance System:</div> <div>Transponders:</div> <div>Multi-Function Display:</div> <div>EGPWS:</div> <div>Radar:</div> <div>Emergency Locator Transmitter:</div> </div> <div> <div>Dual Honeywell RNZ-850</div> <div>Dual Honeywell DF-850</div> <div>Honeywell Primus P1000</div> <div>Honeywell Primus P1000</div> <div>Universal UNS 1CSP</div> <div>Dual Honeywell Primus 1000 IC 600</div> <div>Honeywell ALT-55B</div> <div>Dual Honeywell 850</div> <div>Fairchild A200S</div> <div>Dual Honeywell AZ-850</div> <div>Aircell ST-3100</div> <div>Dual Honeywell RCZ-851</div> <div>Honeywell TPU-67A TCAS II</div> <div>Dual Honeywell XS-852 Mode S</div> <div>Triple Honeywell DU-8870</div> <div>Honeywell Mark VII</div> <div>Honeywell Primus P880 Color</div> <div>Artex 110-406 ELT</div> </div>		
MAINTENANCE:	• On Computerized Maintenance Program		
INTERIOR:	Eight passenger executive interior completed in Beige leather with Sand carpet. Four (4) forward facing seats with two (2) aft facing seats, forward two (2) place side facing divan, forward refreshment center, forward cabin monitor Collins Airshow 400, three (3) 110V Outlets, Non-belted, externally servicing Lav, EROS Crew Oxygen Masks. Refurbished in 2015.		
EXTERIOR:	Overall White with Blue and Maroon.		



Aircraft offered subject to prior sale, inspection, verification of specifications and withdrawal from market. REV08122024mjh

Chicago, Illinois • St. Paul Downtown Airport
www.GenAv.com • Sales@GenAv.com



• ph: 847-726-5000 • fx: 847-726-7673



GENERAL AVIATION SERVICES, LLC



Aircraft Specifications - Citation Excel, s/n 5135
Continued Page 2 of 4

2000 CITATION EXCEL



Chicago, Illinois • St. Paul Downtown Airport
www.GenAv.com • Sales@GenAv.com

GenAv.com

• ph: 847-726-5000 • fx: 847-726-7673



GENERAL AVIATION SERVICES, LLC



Aircraft Specifications - Citation Excel, s/n 5135
Continued Page 3 of 4

2000 CITATION EXCEL



Chicago, Illinois • St. Paul Downtown Airport
www.GenAv.com • Sales@GenAv.com

GenAv.com

• ph: 847-726-5000 • fx: 847-726-7673



GENERAL AVIATION SERVICES, LLC



Aircraft Specifications - Citation Excel, s/n 5135
Continued Page 4 of 4

2000 CITATION EXCEL



Chicago, Illinois • St. Paul Downtown Airport
www.GenAv.com • Sales@GenAv.com

GenAv.com

• ph: 847-726-5000 • fx: 847-726-7673